








Mounting instructions

W016121 R02

6. 4 x M8x40



7. 2 x M8x16

8. MIG 4 x M5x12  
4 x M5x12TIG 4 x M5x12  
2 X M5x12