







1.





M8x16

2.




4 x Ø20


3.



4. 4 x M6x12




MIG



TIG

5. 8 x M8x16




userdoc.kemppi.com








Mounting instructions

W016123 R04

6. 4 x M8x40



7. 4 x M8x16

8. MIG 4 x M5x12
4 x M5x12TIG 4 x M5x12
2 X M5x12

Mounting instructions

W016123 R04