







1. 4 x M6x12



4 x M6x12




2. 8 x M8x16





MIG

3.




4 x M5x12






TIG

3.



2 x M5x12


userdoc.kemppi.com

Mounting instructions

W016124 R02